

Table of Contents

1. Thrufeed: Irregularities in Cylindricity and Straightness.	1
Definition of cylindricity and straightness	1
Bend of workpiece (BOW).....	1
Example for carbon steel parts	3
Various factors can have influence on BOW correction	4
Taper over workpiece length	5
Barrel shape.....	7
Low center	9
Low end on workpiece	10
2. Thrufeed: Irregular Size Holding.	12
Out of round or size variance.....	12
Part to part size variance	12
Irregular size adjustments.....	13
Sudden part size changes.....	16
Parts trend to go undersize.....	17
3. Thrufeed Out of Roundness.....	19

Table of Contents

Definition and types of out of roundness.....	19
Part configuration and out of roundness	20
Regulating wheel quality and out of roundness.....	21
Mounting of regulating wheel	21
Machine errors and out of roundness.....	22
4. Thrufeed: Surface Finish and Irregularities.	25
Surface finish too high	25
Large surface finish variance.....	27
Sudden surface finish changes	29
Feed lines type of surface finish irregularities.....	30
End chatter	32
Spiral barb wire type irregularity (pick up on blade) .	33
Spiral diamond line	34
Inconsistency after each dress	35
5. Thrufeed: Workpiece Burn.....	37
Surface integrity definition	37
Hardness alterations.....	37
Residual stresses.....	37
Recrystallization.....	38
Causes of Burn	38

6. Thrufeed: Chatter	42
Forced vibrations	42
Self exciting chatter	44
7. Infeed: Cylindricity and Straightness Irregularities.	48
Definition of cylindricity and straightness.....	48
Bend Of Workpiece (BOW)	48
Taper over workpiece length	50
Barrel shape.....	53
Low center	56
Step errors	57
8. Infeed: Irregular size holding.	58
Out of round or size variance.....	58
Part to part size variance	58
Irregular size adjustments.....	60
How to define size compensation variance.....	60
Sudden part size changes.....	61
Parts trend to go undersize.....	62
9. Infeed: Out of Roundness.	65
Part configuration and out of roundness	65
Regulating wheel quality and out of roundness	67

Table of Contents

Regulating wheel and workrest blade support and out of roundness:.....	68
Regulating Wheel Support Errors.....	68
Workrest blade support error	70
Machine errors and out of roundness.....	71
Chatter and out of roundness	74
10. Infeed: Workpiece Burn.....	76
Surface integrity definition	76
Hardness Alterations	76
Residual Stresses	76
Recrystallization.....	77
Causes of burn	77
11. Infeed: Chatter.	81
Forced vibrations	81
Self exciting chatter	82
Truing technology.....	85
12. Work Guide Adjustment for Thrufeed Grinding..	87
Work guide adjustments for thrufeed work.....	87
Taper on the front end.....	91
Taper on the rear end.....	92

Low in center	92
13. Surface Finish Nomenclature.....	94
Surface finish	94
The Mechanics of measurement.....	95
Surface texture symbols	96
Bearing ratio and skewness	99
Guide to surface roughness values for equivalent dimensional tolerances.....	100
14. Tooling Selection.	101
Diamond Tooling.....	101
Double Blade Diamond	101
Single Blade Diamonds.....	102
Synthetic Diamonds.....	105
Regulating Wheels	107
15. Truing Angle and Diamond Holder Setting.....	108
16. Thrufeed Rate Calculations	109
Index.....	112